


Tabulka spotřeby spon a klínů Fixlevel

| X cm | Tabulka spotřeby spon a klínů Fixlevel | | | | | | | | | | | | | |
|------|--|----|----|----|----|----|----|----|----|----|----|----|-----|----------|
| 10 | 200 | | | | | | | | | | | | | |
| 15 | 133 | 89 | | | | | | | | | | | | |
| 20 | 100 | 67 | 50 | | | | | | | | | | | |
| 25 | 80 | 53 | 40 | 32 | | | | | | | | | | |
| 30 | 100 | 67 | 50 | 40 | 44 | | | | | | | | | |
| 33 | 91 | 61 | 45 | 36 | 40 | 37 | | | | | | | | |
| 40 | 75 | 50 | 37 | 30 | 33 | 30 | 25 | | | | | | | |
| 45 | 67 | 44 | 33 | 27 | 30 | 27 | 22 | 20 | | | | | | |
| 50 | 60 | 40 | 30 | 24 | 27 | 24 | 20 | 18 | 16 | | | | | |
| 60 | 50 | 33 | 25 | 20 | 22 | 20 | 17 | 15 | 13 | 11 | | | | |
| 80 | 50 | 33 | 25 | 20 | 21 | 19 | 16 | 14 | 12 | 10 | 9 | | | |
| 90 | 44 | 30 | 22 | 18 | 19 | 17 | 14 | 12 | 11 | 9 | 8 | 7 | | |
| 100 | 50 | 33 | 25 | 20 | 20 | 18 | 15 | 13 | 12 | 10 | 9 | 8 | 8 | |
| 120 | 42 | 28 | 21 | 17 | 17 | 15 | 13 | 11 | 10 | 8 | 7 | 6 | 7 | 6 |
| | 10 | 15 | 20 | 25 | 30 | 33 | 40 | 45 | 50 | 60 | 80 | 90 | 100 | 120 Y cm |



$X (60\text{ cm}) ; Y (80\text{ cm}) =$

$10ks / m^2$

ChmelikTrade.cz